...219/2017-18, dt. 10.01.2018

BRUHAT BANGALORE MAHANGARA PALIKE

Inspection Report

1	Name Of Work:	Removal of Debris and Desilting of Drain in ward no 16 Jalahalli in Yeshwanthapura Sub division
2	Administration Approval & Date	EE/RRND/AS/43/2017-18 Dtd: 03.07.2017
3	Technical Sanction Estimate No. & Date	EE/RRND/TS/12/2017-18 Dtd: 03.07.2017
4	Estimate Amount	10,00,000/-
5	Job Code No.	016-17-000003
6	P-Code	P-1771 Zone works- POW Works
7	Agreement No and Date:	EE/RRND/Agmt/104/17-18 Dtd: 03.10.2017
8	Work order Number & Date	EE/RRND/WO/000014/17-18 Dtd: 04.10.2017
9	Contract Amount as per Agreement	Rs. 9,99,969/-
10	Bill Amount	Rs. 9,99,969/-
11	B.R No. & Date	23/28.04.2018
12	Agency	M/s MATI Constructions
13	M.B. Number & Page No. of Measurement records	3663/15-16 Page No 366240 to 366241
14	Date of Inspection	28.04.2018
15	Enclosures	4 Number of photos taken during inspection
16	The above site Location has been Inspected by me along with the Concerned person. The Items indicated in the MB are not Susceptible for measurements, as such the photos taken during the execution Inspection Report of work have been scrutinised and Inspected It appears that the above work has been done. This has a reference to EE(RRND) Letter no EE/RAN/PR/26/17-18 Dated 26-4-2018.	

28/4/2018

(R. Sathyanarayana)
Inspection Report Officer.

R. SATHYANARAYANA
INSPECTION OFFICER

EE (RR) Dividion, RR Nagara Zone.

ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ರಾಜರಾಜೇಶ್ವರಿನಗರ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬೆಂಗಳೂರು - 560...

Scanned by CamScanner